

TEST REPORT

CheckCode:703330
Report No.:C202511262469-22E

Company Name: Shanghai Eastsoft Microelectronics Co.,Ltd.
Address: 3rd Floor, Building 12,Phoenix Park, No.1515 Gumei Road, Xuhui District,Shanghai.

The following sample information is provided by the client and responsible for its authenticity

Sample Name: SOP chip
Material: SOP8
Sample State: Normal

Date of Receipt: Dec.2,2025 **Test Period:** Dec.2,2025 – Dec.9,2025

Test Request: Halogen

Judge Standard: EN 61249-2-21:2003

Test Result: Please refer to following page(s).

Conclusion: Based on the performed test on submitted sample, the result(s) comply with the limits as set by EN 61249-2-21:2003.

Edited by Yan Xiaolan Reviewed by Huang Yingkun Approved by Zheng Xiaoping



扫一扫 验真伪

Issue date:Dec.9,2025

The result(s) shown in this report refer(s) only to the sample(s) tested. This report is considered invalid without approved signature, special seal for inspection and testing and the seal on the perforation. This report cannot be reproduced except in full, without prior written approval of the company. Any disagreements of the test report should be fed back to us within 15 workdays upon receiving the report. Scan the QR code on the first page of the test report, or log on to the official website <http://www.grgtmail.com>, enter the report number and check code to check the authenticity of the report. If you have any questions, please contact the email grgtest@grgtest.com. GRGT assumes no responsibility for information leakage caused by improper management of the QR code and the check code by customers.

GRG METROLOGY & TEST GROUP CO., LTD.

Add: No.8,Chuangyun Road,Panyu District,Guangzhou,Guangdong,China
Tel: 4006020999 Fax: +86-020-38698685 Website: <http://www.grgtest.com>

TEST REPORT

CheckCode:703330
Report No.:C202511262469-22E

Sample description:

| Sample No. | Description |
|------------|-----------------------------------|
| 1 | Black body with silvery metal pin |


Test results:

Test Method: With reference to EN 14582: 2016, analysis was performed by Ion Chromatography.

| Test Item | Sample | Unit | MDL | Limit | Conclusion |
|----------------|--------|-------|-----|-------|------------|
| | 1 | | | | |
| Fluorine (F) | N.D. | mg/kg | 25 | --- | --- |
| Chlorine (Cl) | N.D. | mg/kg | 25 | ≤900 | Comply |
| Bromine (Br) | N.D. | mg/kg | 25 | ≤900 | Comply |
| Iodine (I) | N.D. | mg/kg | 25 | --- | --- |
| Sum of Cl & Br | N.D. | mg/kg | --- | ≤1500 | Comply |

Remark: 1) mg/kg = ppm
2) MDL = method detection limit
3) N.D. = Not Detected (Below method detection limit)


Halogen test process:



TEST REPORT

CheckCode:703330
Report No.:C202511262469-22E

Photo of Sample



-----End of Report-----